

APPENDIX B

Appendix B: Recording and Data Transfer Connections

The Model DL-1 includes cables necessary for data recording and data transfer. The cables are distinct and easily identified.

Data Collection Cable (Sampling Interface Cable)



The Data Recording cables have a serial connector at one end and four pairs of color-coded and labeled clamps at the other end.



Data Transfer Cables

The Data Transfer cable included with the Model DL-1 is a serial cable with a 9-pin connector at one end and a 3-pin round connector at the other. The round connector (3-pin) is always attached to the Model DL-1 and the serial connector (9-pin) is always attached to the computer. You can leave the Data Transfer cable attached to your computer when not in use, and you can attach and detach the DL-1 to the Data Transfer cable without having to turn your computer off. (May not apply to all computer operating systems)

Optional Handspring PDA Cable

For connection of the Model DL-1 Data Logger to a Handspring PDA handheld computer, this optional Data Transfer cable is available.

****NOTE:** This cable is optional and is not included with the standard DL-1 kit.

